



SOURCE: Drost, BW., et.al., 1998. Hydrology and Quality of Groundwater in Thurston County, Washington. USGS Water Resources Investigations Report 92-4109. Figure reproduced from: Well Locations, Surficial & Geohydrology, and Geohydrologic Sections - PLATE 1.

FIGURE **Ö**GEOHYDRAULIC CROSS SECTION: LAKE ST. CLAIR TO NISQUALLY REACH
NISQUALLY TRIBE/WATERSHED PLAN/WA